


INSIGHTS

No.6

Business case #1 Commercial & industrial PV plant

1. Analysis of monitoring data

The annual performance ratio **PR** of the PV plant is stable for the first 5 years of operation, followed by a sharp drop (-25%) in 2018. The loss in performance went nearly unnoticed by the plant owner for nearly 3 years.



38.3 °C 43.3 IR ↓ 16.5



Plant details

- Location: N of Milan (45°N, 9° E)
- Plant description: 450 kWp on commercial warehouse, buildingintegrated PV (BIPV) plant.
- Connection to the grid: 2011
- Business model: Italian's feed-in tariff from 2011 (4th Conto-Energia): 0-43 €/kWh (for building integrated systems)

2. Diagnosis

Thermography highlighted the presence of hot-spots in solar cells, that could be correlated to the presence of sever cracks by performing UV-F (UV-Fluorescence) imaging. Likely the presence of cracked cells can be traced back to a **severe hail event** happened in summer 2018 (please note that none of the modules had broken glass covers). The plant's underperformance went long unnoticed, leading to ~25% lower annual revenues. The on-site inspection was first performed in 2021.



OFFICINA DEL SOLE

TESTING | ANALYSIS | SOLUTIONS

Via Morgagni, 40 - 20010 Pogliano Milanese (Mi) P. IVA 10143840964 N. Verde 800 778 046

www.o-sole.eu | info@o-sole.eu



>>> continued

No.6

Business case #1 Commercial & industrial PV plant

32.3 °C

3. Proposed interventions

- -Full repowering restoring the initial nominal power (i.e. 450 KWp).
- -Full module substitution with newer technology reducing the occupancy of the plant by 25%. The freed space has been used to install more PV increasing self-consumption.
- -The generous feed-in tariff (0.43 €/kWh) and the time left for the incentives (9 years) fully justified economically the intervention.
- -No legal claim was started against the manufacturer for the damaged modules and the non-compliance with warranties. The module manufacturer was not existing any longer.
- -To much time had passed for filing a cla<mark>im with t</mark>he insurance company.

Lessons learnt

- **Check monitoring** data regularly.
- After a **severe hail event** check the modules and the PV plant.
- If the PV plant is **insured**, respect the timeframe for filing a claim with the insurance company.



TESTING | ANALYSIS | SOLUTIONS

Via Morgagni, 40 - 20010 Pogliano Milanese (Mi) P. IVA 10143840964 N. Verde 800 778 046

CONTACT US

www.o-sole.eu | info@o-sole.eu